

TECHNICAL INSPECTIONS, INC.  
 PO BOX 1307  
 LOXAHATCHEE, FL 33470  
 OFFICE (561) 619-5313 FAX (561) 619-5315



INSPECTED BY: Mark Vitale INSPECTION DATE: 7/23/24

SITE / SUBDIVISION NAME: Fox Trail

CULVERT LOCATION: Runs East + West under Lion Country

PIPE SIZE: 48" PIPE LENGTH: 80' TYPE OF CULVERT: RCP  CAP  CMP


DEPTH FROM SURFACE TO THE TOP OF THE PIPE 4"

DESCRIBE ACCESS TO THE PIPE outfall

CHANNELING REQUIRED: YES  NO  ON WHICH SIDE?

PIPE CONDITION: CLEAN  0-3"  0-6"  0-12"  0-18"  3"  3-6"  6"  
 6-12"  12"  12-18"  12-24"  18"  18-24"  24"+

GENERAL CONDITION OF THE PIPE: Pipe appears to be in good Condition. All pipe joints are good and not leaking.



NOTES: No cleaning is needed